

ENCLOSURE 4

ACM REMOVAL AND CLEANUP ACTIVITIES

TABLE E4-1
ACM Removal and Cleanup Activities

Building	Built Prior to 1985	Survey Results	Building Status	Notes
<i>POL Hill Parcel</i>				
715	Yes	Contained asbestos	Demolished	Asbestos removed prior to building demolition by IT Corp.
717	Yes	Not surveyed	Demolished	Building removed during POL Hill Parcel investigation and remediation by IT Corp.
736	Yes	Contained asbestos	Demolished	Prior to building demolition, asbestos was removed by Marcor. Building removed during the construction of the Landfill 26 treatment plant.
737	Yes	Contained asbestos	Demolished	Prior to building demolition, asbestos was removed by Marcor. Building removed during the construction of the Landfill 26 treatment plant.
738	Yes	Contained asbestos	Demolished	Prior to building demolition, asbestos was removed by Marcor. Building removed during the construction of the Landfill 26 treatment plant.
Landfill 26 Treatment Plant	No	NA	Present	Built in 1993 – No asbestos.